

# Site Visit Report

The site visit process is a sample on a particular day of an installation's compliance with some of its licence conditions. Where non-compliance against a particular condition has not been reported, this should not be construed to mean that there is full compliance with that condition of the licence.

Instructions and actions arising from the visit shall be addressed, or where applicable noted, by the licensee in order to ensure compliance, to improve the environmental performance of the installation and to provide clarification on certain issues.

The licensee shall take the actions specified to close out the non-compliances and observations raised in this Site Visit Report.

Licensee	
<b>Name of Installation</b>	The East Tip
<b>Licensee</b>	Minister for Agriculture, Food and the Marine
<b>Licence Register No.</b>	W0289-01
<b>CRO Number</b>	
<b>Site Address</b>	Haulbowline Island, Cork
<b>Site Visit Reference No.</b>	SV08264

Report Detail	
<b>Issue Date</b>	22/12/2016
<b>Prepared By</b>	Joseph Hunter

Site Visit Detail					
Date Of Inspection	23/11/2016	Announced		No	
Time In	10:15	Time Out		13:00	
Agency Personnel On Site	Joseph Hunter				
Licensee Personnel and Role	Justin Power, Resident Engineer, Cork County Council				
Photo Taken	Yes	Samples Taken	No	Video Taken	Yes



## Scope

Planned annual enforcement visit



## Media

Air, Water, ground



## Site Areas Inspected

General site walkover



## Documents Inspected

Safety, Health & Welfare documentation



The facility was closed at the time of the site visit. The licensed activity had not yet commenced.

The licensee confirmed that the remediation project was still at the procurement stage, with construction anticipated to commence in March/April 2017.

Specific requirements of the waste licence were discussed. Particular attention was paid to the environmental monitoring programme to be implemented during the construction phase.

The licensee indicated that a proposal is to be submitted to the Agency, requesting an alteration to the operating hours allowed during the construction phase of the project. According to the licensee this alteration, if agreed, will facilitate the constraints associated with working in a tidal environment.

The site visit was compliant

## **FOLLOW-UP ACTIONS**

You are required to complete the instructions and actions, as outlined in this report, within the specified timeframe. Where required, you shall respond to actions specified in Compliance Investigations within the required timeframe. The licensee shall maintain documentary evidence, for review by the EPA, that the prescribed corrective actions were completed within the required timeframe.

You are not required to respond directly to items contained in this EPA site visit report; where an issue requires a direct response, the EPA will generate a Compliance Investigation through the EDEN system. You will receive notification when a Compliance Investigation instruction or action is generated.

Please note that this Site Visit Report will be made available for public viewing via the EPA's Licence Enforcement Access Portal within one day of the issue date and will be published on the Licence Details Page of the EPA's website, [www.epa.ie](http://www.epa.ie), that relates to your licence 60 calendar days after the issue date.

You may if you choose submit, within 45 calendar days of the issue date of this Site Visit Report, a Licensee Public Response that will be published alongside the Site Visit Report. This Response, should you wish to avail of it, provides you with an opportunity to inform the public about how you are implementing the actions set out in the report, activities underway, timescales and target completion dates. Please be aware that the content of your Licensee Public Response must be factual and should not breach the EPAs stated online publication standards.

If you wish to submit a Licensee Public Response to an EPA Site Visit Report, you should do this by clicking on the 'Make a Response' link on the Site Visits page in EDEN. A .pdf document containing your response can be attached and submitted from here.

Please note that you are required to comply with the conditions of your licence at all times, and where noncompliance occurs you must restore compliance within the shortest possible time. These actions will be verified during subsequent EPA visits.

Please quote the above Inspection Reference Number in any future correspondence in relation to this Report.