

Zawia 1 Snag List

- 1- Ground floor fire man lift corridor damaged skirting, walls & tiles need to be repaired.(Ref, 1,2,3)
- 2- Ground floor fire man lift car light cover need to be provided.(Ref, 4)
- 3- Reception office ceiling access panel need to be repaired.(Ref,5)
- 4- Reception office kitchen door lock to be provided.(Ref,6)
- 5- Reception office kitchen damaged lights to be replaced (4 Nos.)
- 6- Swimming pool damaged valves to be replaced (4 Nos.)
- 7- Swimming Pool Pump vacuum pump need to be re-winded.(Ref,7)
- 8- Swimming pool equipments room aluminum door lock need to be provided.(Ref.8)
- 9- 19th floor common area door handle to be provided (2 Nos.)
- 10- 19th floor common area ceiling damaged paint need to be rectified.(Ref.9)
- 11- 19th floor common area missing sprinkler head to be provided.(Ref.10)
- 12- 19th floor missing power socket covers need to be provided (3 Nos.)(Ref.11)
- 13- 19th floor common area damaged lights to be replaced (5 Nos.)
- 14- 19th floor fire man lift lobby door to be fixed.(Ref.12)
- 15- 18th floor fire man lift lobby door broken glass need to be provided (armored 60x40 cm).
(Ref.13)
- 16- 18th floor fire man lift area burned power socket to be replaced.(Ref.14)
- 17- 18th floor common area damaged lights to be replaced (3 Nos.)
- 18- 17th Floor common area corridor fire hose reel pressure regulating valve access panel to be provided.(ref.15)
- 19- 17th floor Damaged lights to be replaced (5 Nos.)
- 20- 16th floor fire man lift lobby damaged light fitting to be replaced.(Ref.16)
- 21- 16th floor common area damaged lights to be replaced (8 Nos.)
- 22- 15th floor common area damaged lights to be replaced (7 Nos.)
- 23- 14th floor common area damaged lights to be replaced (8 Nos.)
- 24- 14th floor fire man lift lobby damaged light switch to be replaced.(Ref.17)
- 25- 13th floor common area damaged lights to be replaced (8 Nos.)
- 26- 12th floor common area damaged lights to be replaced (9 Nos.)
- 27- 12th floor common area missing access panel to be provided.(Ref.18)
- 28- 11th floor common area damaged lights to be replaced (8 Nos.)
- 29- 10th floor common area damaged lights to be replaced (5 Nos.)
- 30- 10th floor common area missing smoke detector cover to be provided.(Ref.19)
- 31- 9th floor common area damaged lights to be replaced (8 Nos.)
- 32- 8th floor common area damaged lights to be replaced (6 Nos.)
- 33- 7th floor common area damaged lights to be replaced (8 Nos.)
- 34- 7th floor fire man lift lobby broken light fitting cover to be replaced.(Ref.20)
- 35- 6th floor common area damaged lights to be replaced (4 Nos.)
- 36- 6th floor corridor ceiling diffuser cover to be replaced.(Ref.21)
- 37- 6th floor fire man lift light fitting cover to be replaced.(Ref.22)
- 38- 5th floor common area damaged lights to be replaced (7 Nos.)
- 39- 4th floor common area damaged lights to be replaced (8 Nos.)
- 40- 3rd floor common area damaged lights to be replaced (9 Nos.)
- 41- 3rd floor staircase light fitting cover to be replaced.(Ref.23)
- 42- 2nd floor common area damaged lights to be replaced (7 Nos.)
- 43- 1st floor common area damaged lights to be replaced (5 Nos.)

44- Ground floor common area damaged lights to be replaced (6

Nos.)

45- Ground floor light switch to be replaced.(Ref.24)

46- Basement floor corridor damaged fluorescent lights to be provided.(Ref.25)

47- Gents Gym bathroom WC spray hose to be provided.(Ref.26)

48- Gents Gym bathroom damaged lights to be provided (5 Nos.)(Ref.27)

49- Gents sauna room damaged lights to be replaced (2 Nos.)

50- Gents steam room damaged light to be replaced (1No.)

51- Basement floor damaged water tank to be repaired.











52- Roof water tank leak to be repaired.

53- Store rooms missing locks to be provided (8Nos.)(Ref.28)

54- Telecom rooms missing door locks to be provided (6Nos.)(Ref.29)

55- Electric room door missing locks to be changed (14 Nos.)(Ref.30)

56- Missing Chilled water BTU meters in flats & commercial areas to be provided (8Nos.)

1		17	
2		18	
3		19	
4		20	
5		21	

6		22	
7		23	
8		24	
9		25	
10		26	
11		27	

1 2		28	
1 3		29	
1 4		30	
1 5			
1 6		6	

