



Vehicle Inspection Service

Report NO. 111103-181073043

Date: November 04, 2011

5590 Goring Street, Burnaby, B.C. V5B 3A3
Tel: 604-298-2755

IMPORTANT PLEASE READ:

THIS IS NOT A VEHICLE CERTIFICATION

This report provides information to the recipient on the observed condition of this vehicle AS OF THE INSPECTION DATE AND TIME INDICATED covering systems and components noted below.

NO OPINION OR ADVICE IS GIVEN AS TO WHETHER THIS VEHICLE SHOULD BE PURCHASED OR REPAIRED.

This report is for the recipient's information only and is not a certification, warranty, guarantee or endorsement for any purpose whatsoever, and BCAA assumes no liability whatsoever in respect thereof. The report may in fact disclose serious vehicle deficiencies. The inspection covered by this report is VISUAL ONLY, aided by instruments. No responsibility can be accepted for defects or conditions which may be discovered by road-testing or by dismantling of components or parts whether or not included in this inspection, or hidden by bodywork, paint, or undercoat.

BCAA reserves the right to re-inspect this vehicle before any repairs that are a deviation from or an addition to those noted in this report are performed.

Table with vehicle details: NAME: MR BCAA, YEAR: 2008, MAKE: HONDA, MODEL: CIVIC, TYPE, CYLINDERS: 4, ODOMETER READING: 50000.0 KM, TRAILER HITCH: NO, UNDERCOATED: NO, V.I NUMBER: IHGMSU212XXXXXXX, CAR COLOUR: RED, STOCK NUMBER, OVERVIEW REQUEST, PURCHASE ORDER NUMBER.

Legend table: U Unsatisfactory/Defect - Requires immediate attention/repair as required, A Advisory - Details listed, requires attention, S Satisfactory - No apparent defect detected, N Not applicable - This item on the checklist is not applicable to this vehicle



Body

Body inspection table with 10 items: 1. Exterior body and paint (S), 2. Underbody (S), 3. Frame (S), 4. Trunk (S), 5. Mirrors (S), 6. Bumpers (A) See Comment Box, 7. Windshield (A) Chips, 8. L/F Windows Winder (S), 9. Hood Latch/Supports (S), 10. Driver Seat (S)

Electrical System

Electrical System inspection table with 18 items: 11. Horn (U) Not Working, 12. Headlights (S), 13. Taillights (S), 14. Stop Light (S), 15. Parking Lights (S), 16. Marker Lights (S), 17. Emergency Flasher (S), 18. Turn Signals (S), 19. Licence Plate Light (S), 20. Neutral Switch (S), 21. Wipers (S), 22. Washers (S), 23. Wiper Arm (S), 24. Heater/Defroster (Front) (S), 25. Starter (S), 26. Battery (S), 27. Charging Voltage (S), 28. Instrument Panel (S)

Engine

Engine inspection table with 13 items: 29. Engine Oil (S), 30. Valve Cover (S), 31. Cylinder head/Intake Manifold area (S), 32. Rear Seal (A) Clean & Recheck, 33. Oil Pan (S), 34. Front seal area (S), 35. Oil Filter (S), 36. Oil Pressure sender (S), 37. PCV filter/Valve/hose (S), 38. Engine Mounts (S), 39. Belts (S), 40. Oil Burning (S), 41. Blow By (S), 42. Engine Operation (S), 43. Ignition System (S)

*FOR ADDITIONAL INFORMATION ON ANY VEHICLE, RESEARCH CONSUMER REPORTS. www.bcaa.com/usedcars

*NEED REPAIRS OR SERVICE? FIND A BCAA APPROVED FACILITY AT www.bcaa.com/aars

*RIGHT SIDE BRAKES CHECKED ONLY.

*NO AIR CARE RESULTS.

*BRAKE AND TIRE WEAR IS IN ESTIMATED PERCENTAGE.

*ITEM # 39 BELTS: CONSULT VEHICLE OWNER'S MANUAL FOR RECOMMENDED TIMING BELT REPLACEMENT INTERVALS IF APPLICABLE.

THE EMISSION CONTROL COMPONENTS ON THIS VEHICLE HAVE BEEN VISUALLY INSPECTED. THE INSPECTION RESULTS CANNOT BE INTERPRETED AS A PASS OR FAIL FOR THE BC AIR CARE PROGRAM. FOR CERTIFICATION THE VEHICLE MUST BE TESTED AT AN AIR CARE STATION

*LIMITED ACCESS TO MANUFACTURERS COMPUTER CODES.

Cooling System

S	44. Coolant
S	45. Pressure test
S	46. Radiator
S	47. Radiator Cap
S	48. Water Pump
S	49. Upper Hose
S	50. Lower Hose
S	51. Heater Hoses
S	52. By-Pass Hose
S	53. Clutch Fan
S	54. Clutch
S	55. Shroud
S	56. Frost Plugs
S	57. Expansion Tank

Fuel System

S	58. Fuel Injection
S	59. Accelerator Pedal
S	60. Linkage/Controls
S	61. Air Cleaner/Filters
S	62. Pre-heat/fresh air duct
S	63. Fuel Lines
S	64. Fuel Tank

Rear Suspension

S	105. Springs/Shackles/Torsion Bar/Track Rod RH/LH
S	106. Ball Joint/Control Arm/Trailing Arm/Bushings RH/LH
S	107. Tie Rod Ends/Outer Inner RH/LH
S	108. Stabilizers/Bushings RH/LH
S	109. McPherson Strut
S	110. Shock Absorber/Bushings RH/LH
S	111. Axle Housing/Mount RH/LH
S	112. Wheel/Axle Bearing RH/LH

Driveline

S	65. Auto Trans Fluid Level/Condition
S	66. Clutch/Linkages/Slave
S	67. Shift Indicator
S	68. Shift Linkage
S	69. Transmission Fluid Pan
S	70. Transmission Front Seal Area
S	71. Rear Extension Housing/Seal
S	72. Speedo Drive
S	73. Transmission Mount
S	74. Cooler Lines
S	75. CV Joint/Boot
S	76. U-Joints/Coupling
S	77. Slip Yoke/Joint
S	78. Axle Bearing
S	79. Axle Seal
S	80. Differential-Pinion Seal/Area
S	81. Transfer Case Seal/Gasket

Steering & Front Suspension

A	82. Alignment	4 Wheel Alignment Check Required
S	83. Control Arm Upper/Lower	
S	84. Track Rod Bushing Right/Left	
S	85. Ball Joints Lower R/Hand-L/Hand	
S	86. Ball Joints Upper R/Hand-L/Hand	
S	87. Steering Box Sector Shaft Bushing	
S	88. Column Shaft/Coupling	
S	89. Steering Lash	
S	90. Tie Rod Ends Outer/Inner, LH/RH	
S	91. Drag/Center Links	
S	92. Idler Arm/Pitman Arm	
S	93. Springs/Shackles, Torsion Bar RH/LH	
S	94. Steering Damper/Ram	
S	95. McPherson Strut RH/LH	
S	96. Shock Absorber/Bushings RH/LH	
S	97. Strut Rod/Bushings RH/LH	
S	98. Stabilizer/Bushings RH/LH	
S	99. Power Steering Pump/Level	
S	100. Power Steering Hoses	
S	101. Power Steering Operation	
S	102. Rack & Pinion/Bellow/Bushing/Bracket	
S	103. Wheel/Axle Bearing RH/LH	
S	104. Radius Arm Bushing	

Exhaust System

S	113. Exhaust Manifold
S	114. Exhaust Pipes
S	115. Muffler
S	116. Resonator
S	117. Catalytic Converter
S	118. Tail Pipe
S	119. Hanger/Clamps

Wheels and Tires

S	131. Wheels and Tires: Left Front
S	132. Wheels and Tires: Right Front
S	133. Wheels and Tires: Left Rear
S	134. Wheels and Tires: Right Rear
S	135. Spare
S	136. Wheel Rims
S	137. Wheel Covers
S	138. Studs, Nuts RH

Brakes

S	120. Brake Pedal Reserve
S	121. Master Cylinder
S	122. Power Assist
S	123. Lines/Hoses LF/RF/Rear
S	124. Front Brake Disc's
S	125. Rear Brake Disc/Drum
S	126. Brake Lining/Pads Right Front
S	127. Rear Brake Shoes/Pads
S	128. Park Brake Operation
S	129. Front Calipers
S	130. Calipers Wheel Cylinder/RR

Road Test

S	139. Transmission Operation
S	140. Clutch Operation
S	141. Driveline/Noise Vibration
S	142. Service Brake Performance
S	143. Steering Operation

DATE: November 04, 2011

DRIVER NAME:

CONTACT PHONE: 604-298-2755 (office)

For overview of report please contact the Association

TECH NOTES:

INSPECTOR'S SIGNATURE:

Carlos

***It has been confirmed that vehicle wheel nuts have been tightened after inspection**



Vehicle Inspection Service

MEMBER'S NAME: MR BCAA

Report NO. 111103-181073043

VEHICLE MAKE, Model & TYPE: HONDA-CIVIC-

ADDITIONAL INSPECTION COMMENTS

Question	Comments
6. Bumpers	front lower area of cover, scrape and cracked
27. Charging Voltage	14.5 Volts
32. Rear Seal	Clean residue/wetness off and monitor for seeps
44. Coolant	-32 Celsius
131. Wheels and Tires: Left Front	(50_ % _mm)
132. Wheels and Tires: Right Front	(50_ % _mm)
133. Wheels and Tires: Left Rear	(40_ % _mm)
134. Wheels and Tires: Right Rear	(50_ % _mm)
126. Brake Lining/Pads Right Front	(50_ % _mm)
127. Rear Brake Shoes/Pads	(65-70_ % _mm)



Vehicle Inspection Service

MEMBER'S NAME: MR BCAA

Report NO. 111103-181073043

VEHICLE MAKE, Model & TYPE: HONDA-CIVIC-

ADDITIONAL INSPECTION PHOTOS

PHOTO #1

PHOTO #2

PHOTO #3

PHOTO #4